Department of Engineering Dan Gaillet, P.E., County Engineer 3137 South Liberty Street, Canton, MS 39046 Office (601) 790-2525 FAX (601) 859-3430

MEMORANDUM

January 31, 2018

To:

Sheila Jones, Supervisor, District I Trey Baxter, Supervisor, District II Gerald Steen, Supervisor, District III David Bishop, Supervisor, District IV Paul Griffin, Supervisor, District V

From: Dan Gaillet, P.E. County Engineer

Re:

Sink Hole

111 Parkfield Place Ridgefield Subdivision

A sink hole has formed due to the failure of a 36" concrete pipe that carries roadway storm water from Parkfield Place to a detention pond, across private properties at 109 and 111 Parkfield Place.

The Engineering Department suspects that the pipe has separated which is causing a dangerous sink hole. However, a full determination of damage will take place after authorization is granted to work on private property.

It is the recommendation of the Engineering Department that the Board authorize repairs to ensure that storm water is moved from point-to-point to prevent damage to the roadway and further damage to the storm water system.

Therefore, it is in the best interest of the County and the public's health, safety and welfare to make the repairs, based on:

- Separated storm water pipes; and
- Water is unable to flow freely off of Parkfield; and
- A large sink hole has formed over the failed pipes.

SHEILA JONES District One

TREY BAXTER District Two


GERALD STEEN District Three


DAVID BISHOP District Four

PAUL GRIFFIN District Five


SINKHOLE FLOW CHART

LOCATION: /// Revefield Place





-20' Drainage Fasement



Google Earth

feet 300 neters 100

