

P. O. BOX 1850 JACKSON, MISSISSIPPI 39215-1850

H. Carey Webb, P.E. State Aid Engineer Tele 601-359-7150 www.msstateaidroads.us

V

412 Woodrow Wilson Ave. Jackson, Mississippi 39216 Fax 601-359-7141 mail@osarc.ms.gov

January 12, 2018

Board of Supervisors Madison County P. O. Box 608 Canton, MS 39046-0608

> RE: Partial Bridge Closure Structure Number: SA450000000086 Sharon Road, Sec. 6, T9N, R4E Madison County

Supervisors:

This letter is to inform you that based on the findings of the recent inspection, the Southbound Lane of the above referenced bridge site should be immediately closed by appropriate emergency/temporary means in accordance with the **Critical Finding Procedure for County** / **City Bridges Part 4** (attached).

Once the bridge is closed using these emergency/temporary means, the County Engineer should be notified and digital photographs of the closure shall be forwarded by mail or email to the County Engineer and State Aid for documentation of the closure and placement in the bridge file.

If the bridge has not been repaired within 45 days, no later than **February 26, 2018**, then the bridge should be fully closed in accordance with the State Aid Standard drawing **SA-BC-1** (attached). Digital photographs should be taken in both directions at the bridge, of each advance warning sign and identified by the bridge structure number.

Madison County Board of Supervisors January 12, 2018 Page 2

These photographs should be forwarded by mail or email to the County Engineer and State Aid for documentation of the closure and placement in the bridge file.

If the County has already taken action on this bridge, please provide the necessary documentation as indicated above. If the County can provide adequate written justification to warrant additional time for repair of the bridge or installation of the standard signs, barricades or barriers, an extension of time may be considered by State Aid.

Any questions concerning this should be discussed with your County Engineer.

Sincerely,

H. Carey Webb, P. E. State Aid Engineer

C David Banet

By: C. David Barrett NBI Program Manager

CDB/jaa Attachments

pc: James L. Hust, III, P. E., County Engineer (w/ attachments)
Ronny Lott, Chancery Clerk (w/ attachments)
Ed Holland, P.E., District Engineer (w/o attachments)
Austin Banks, P.E., FHWA Division Bridge Engineer (w/o attachements)
File



P. O. BOX 1850 JACKSON, MISSISSIPPI 39215-1850

H. Carey Webb, P.E. State Aid Engineer Tele 601-359-7150 www.msstateaidroads.us

412 Woodrow Wilson Ave. Jackson, Mississippi 39216 Fax 601-359-7141 mail@osarc.ms.gov

January 12, 2018

Board of Supervisors Madison County P. O. Box 608 Canton, MS 39046-0608

> RE: Partial Bridge Closure Structure Number: SA450000000088 Robinson Road, Sec. 18, T9N, R4E Madison County

Supervisors:

This letter is to inform you that based on the findings of the recent inspection, the Westbound Lane of the above referenced bridge site should be immediately closed by appropriate emergency/temporary means in accordance with the **Critical Finding Procedure for County** / **City Bridges Part 4** (attached).

Once the bridge is closed using these emergency/temporary means, the County Engineer should be notified and digital photographs of the closure shall be forwarded by mail or email to the County Engineer and State Aid for documentation of the closure and placement in the bridge file.

If the bridge has not been repaired within 45 days, no later than **February 26, 2018**, then the bridge should be fully closed in accordance with the State Aid Standard drawing **SA-BC-1** (attached). Digital photographs should be taken in both directions at the bridge, of each advance warning sign and identified by the bridge structure number.

Madison County Board of Supervisors January 12, 2018 Page 2

11.0

These photographs should be forwarded by mail or email to the County Engineer and State Aid for documentation of the closure and placement in the bridge file.

If the County has already taken action on this bridge, please provide the necessary documentation as indicated above. If the County can provide adequate written justification to warrant additional time for repair of the bridge or installation of the standard signs, barricades or barriers, an extension of time may be considered by State Aid.

Any questions concerning this should be discussed with your County Engineer.

Sincerely,

H. Carey Webb, P. E. State Aid Engineer

( David Banet

By: C. David Barrett NBI Program Manager

CDB/jaa Attachments

 pc: James L. Hust, III, P. E., County Engineer (w/ attachments) Ronny Lott, Chancery Clerk (w/ attachments)
 Ed Holland, P.E., District Engineer (w/o attachments)
 Austin Banks, P.E., FHWA Division Bridge Engineer (w/o attachements)
 File



P. O. BOX 1850 JACKSON, MISSISSIPPI 39215-1850

H. Carey Webb, P.E. State Aid Engineer Tele 601-359-7150 www.msstateaidroads.us

412 Woodrow Wilson Ave. Jackson, Mississippi 39216 Fax 601-359-7141 mail@osarc.ms.gov ł

January 11, 2018

Honorable Arnel D. Bolden Mayor, City of Canton P.O. Box 1605 Canton, MS 39046-1605

> RE: Bridge Closure Structure Number: SA450000000071 Location: King Ranch Road over Creek, Section 23, T9N, R2E

Dear Mayor Bolden:

This letter is to inform you that the above referenced bridge site has been closed with emergency/temporary means in accordance with the **Critical Finding Procedure for County** / **City Bridges Part 4** (attached). Until such time as the bridge is repaired or replaced the bridge should remain closed. Once the bridge is closed using these emergency/temporary means, the County Engineer should be immediately notified and digital photographs of the closure shall be forwarded by mail or email to the County Engineer and State Aid for documentation of the closure and placement in the bridge file.

Action to begin proper closure should begin immediately and completed by no later than **February 25, 2018** and in accordance with the State Aid Standard drawing **SA-BC-1** (attached). Digital photographs should be taken in both directions at the bridge, of each advance warning sign and identified by the bridge structure number. These photographs should be forwarded by mail or email to the County Engineer and State Aid within 45 days for documentation of the closure and placement in the bridge file.

Orgensi Carran Street antia Sacara Barace Micacara Rapo s

(virespace) and the start sensities and the second start of the second start end of the second start second start is the second start of the se

and a second A second second

•••••

A. College Willer B. E. Searchist Ungellier

ni Angelige and angelige ar a san a<mark>n da ba</mark>rant. Alar ar ar ar ar ar ar ar ar ar

(4) Andreas Sheers for the character of some the associate composition of the formula of the

City of Canton Honorable Arnel D. Bolden January 11, 2018 Page 2

If the City has already taken action on this bridge, please provide the necessary documentation as indicated above. Any repairs to the bridges should be re-inspected by a qualified bridge inspector and the documentation entered into the bridge records prior to reopening the bridge. If the City can provide adequate written justification to warrant additional time for installation/repair of the standard signs, barricades or barriers, an extension of time may be considered by State Aid. Failure to close the bridge in the interest of public safety could jeopardize future Federal funding to the city.

Any questions concerning this should be discussed with your County Engineer.

Sincerely,

H. Carey Webb, P. E. State Aid Engineer

Auril Banet

By: C. David Barrett NBI Program Manager

CDB/jaa Attachments

pc: Lawrence Morris, Public Works Director (w/ attachments)
James L. Hust, III, P. E., County Engineer (w/ attachments)
Board of Supervisors (w/o attachments)
Ed Holland, P.E., District Engineer (w/o attachments)
Austin Banks, P.E., FHWA Division Bridge Engineer (w/o attachments)
File



P. O. BOX 1850 JACKSON, MISSISSIPPI 39215-1850

H. Carey Webb, P.E. State Aid Engineer Tele 601-359-7150 www.msstateaidroads.us

412 Woodrow Wilson Ave. Jackson, Mississippi 39216 Fax 601-359-7141 mail@osarc.ms.gov

January 11, 2018

Board of Supervisors Madison County P. O. Box 608 Canton, MS 39046-0608

> RE: Bridge Closure Madison County

1

Supervisors:

This letter is to inform you that it has been determined the following bridge sites should be immediately closed by appropriate emergency/temporary means in accordance with the **Critical Finding Procedure for County / City Bridges Part 4** (attached).

SA450000000029,	Gluckstadt Road,	Sec. 21, T8N, R2E
SA450000000105,	Tithelo Road,	Sec. 11, T10N, R3E

Until such time as the bridges are repaired or replaced these bridges should remain closed. Once the bridges are closed using emergency/temporary means, the County Engineer should be notified and digital photographs of the closures shall be forwarded by mail or email to the County Engineer and State Aid (mail@osarc.ms.gov) for documentation of the closure and placement in the bridge file.

Madison County Board of Supervisors January 11, 2018 Page 2

8

After the initial emergency/temporary closures, action to begin proper closures should begin immediately and completed by no later than February 25, 2018 and in accordance with the State Aid Standard drawing SA-BC-1 (attached). Digital photographs should be taken in both directions at each bridge site, of each advance warning sign and identified by the bridge structure number. These photographs should be forwarded by mail or email to the County Engineer and State Aid within 45 days for documentation of the closure and placement in the bridge file.

If the County has already taken action on these bridges, please provide the necessary documentation as indicated above. If the County can provide adequate written justification to warrant additional time for repair of these bridges or installation of the standard signs, barricades or barriers, an extension of time may be considered by State Aid.

Any questions concerning this should be discussed with your County Engineer.

Sincerely,

H. Carey Webb, P. E. State Aid Engineer

Chavid Barret

By: C. David Barrett NBI Program Manager

CDB/jaa Attachments

 pc: James L. Hust, III, P. E., County Engineer (w/ attachments) Ronny Lott, Chancery Clerk (w/ attachments) Ed Holland, P.E., District Engineer (w/o attachments) Austin Banks, P.E., FHWA Division Bridge Engineer (w/o attachements) File



P. O. BOX 1850 JACKSON, MISSISSIPPI 39215-1850

H. Carey Webb, P.E. State Aid Engineer Tele 601-359-7150 www.msstateaidroads.us

412 Woodrow Wilson Ave. Jackson, Mississippi 39216 Fax 601-359-7141 mail@osarc.ms.gov

1.

January 11, 2018

Board of Supervisors Madison County P. O. Box 608 Canton, MS 39046-0608

> RE: Partial Bridge Closure Structure Number: SA450000000147 Rocky Hill Road, Sec. 25, T12N, R5E Madison County

Supervisors:

This letter is to inform you that based on the findings of the recent inspection, the South side of the above referenced bridge site should be immediately closed by appropriate emergency/temporary means in accordance with the **Critical Finding Procedure for County** / **City Bridges Part 4** (attached).

Once the bridge is closed using these emergency/temporary means, the County Engineer should be notified and digital photographs of the closure shall be forwarded by mail or email to the County Engineer and State Aid for documentation of the closure and placement in the bridge file.

If the bridge has not been repaired within 45 days, no later than February 25, 2018, then the bridge should be fully closed in accordance with the State Aid Standard drawing SA-BC-1 (attached). Digital photographs should be taken in both directions at the bridge, of each advance warning sign and identified by the bridge structure number.

Madison County Board of Supervisors January 11, 2018 Page 2

These photographs should be forwarded by mail or email to the County Engineer and State Aid for documentation of the closure and placement in the bridge file.

If the County has already taken action on this bridge, please provide the necessary documentation as indicated above. If the County can provide adequate written justification to warrant additional time for repair of the bridge or installation of the standard signs, barricades or barriers, an extension of time may be considered by State Aid.

Any questions concerning this should be discussed with your County Engineer.

11

Sincerely,

H. Carey Webb, P. E. State Aid Engineer

C Durid Barret

By: C. David Barrett NBI Program Manager

CDB/jaa Attachments

 pc: James L Hust, III, P. E., County Engineer (w/ attachments) Ronny Lott, Chancery Clerk (w/ attachments)
 Ed Holland, P.E., District Engineer (w/o attachments)
 Austin Banks, P.E., FHWA Division Bridge Engineer (w/o attachements)
 File