

ESTIMATE VERSION 1 - POSTED TO FLEET

Updated at: 2023-03-15 15:31:12 -0500

Tri-State Truck Center - Mack (Jackson MS)

412 Hwy 49 S. Richland, Mississippi 39218

Phone: (601) 932-3400




Case Number: 16811197

Repair Order Number: 18760

Purchase Order Number: N/A

Service Advisor: Jackson MS-- --Tri-state Service - Case Date 2023-03-13 09:20:16 -0500

Customer: Madison County	Unit Number: 74-14		
Address: PO BOX 237 Madison, FL 32340 Phone: N/A Fax: N/A Customer Number: 4806536140 Billing Customer: Madison County Board Of	Asset: 2015 Mack GU713 Serial Number: FM022304 VIN: 1M2AX04C5FM022304 Engine: MP7	Engine Hours: 11748 Mileage: 185860 Miles Warranty Start: 2014-05-22 12:00:00 -0500 In Service: 8 Years 9 Months	

Item	Operation Name	Parts	Additional Charges	Totals
1	diagnostics			
	Labor:			\$0.00
	Parts:			\$50.00
	-(1.0) P.T.T	\$50.00		\$50.00
2	c/a coolant leak on p.side of engine			
	Complaint:			
	coolant leak on p.side of engine			
	Cause:			
	EGR coolant pipe from EGR cooler to Engine block			
	Correction:			
	Remove EGR cooler and reseal			\$2,283.75
	Labor:			\$2,684.88
	Parts:			\$2,291.40
	-(1.0) EGR COOLER Core: \$390.00	\$2,291.40		\$2,291.40
	-(12.0) RED 50/50 EXTD LIFE COOLANT	\$11.70		\$140.40
	-(1.0) INSTALLATION KIT	\$142.88		\$142.88
	-(1.0) CONNECTION PIPE	\$37.71		\$37.71
	-(1.0) EGR COOLER KIT	\$72.51		\$72.51
3	CEL on Check and advise			
	Labor:			\$385.40
				Labor: \$2,649.15
				Parts: \$2,734.88
				Shop Supplies: \$258.29
				Total: \$5,642.32

Notes:

[3/13/2023 at 09:49 am CDT] - Unit 74-14 was checked in at Tri-State Truck Center - Mack (Jackson MS), arrival time: 3/13/2023 at 09:40 am CDT. NOTE: This is confirmation your unit has been fully checked in. We have a minimum 2-hour assessment / diagnostics. We will update once your unit has been assigned to a technician following up with a repair plan. Thank you.

Repair status set to Checked-In.

[3/15/2023 at 03:31 pm CDT] - Approval Requested for the estimate version 1, total \$5,642.32. View the estimate. NOTE: Mike I have added EGR cooler to estimate just incase if where the pipe goes in is messed up and oring will not seal.

Tri-State Truck Center - Mack (Jackson MS)

412 Hwy 49 S. Richland, Mississippi 39218
 Phone: (601) 932-3400



Case Number: 16791484
 Repair Order Number: 18699
 Purchase Order Number: N/A
 Service Advisor: Jackson MS--


#92 Low boy

--Tri-state Service - Case Date 2023-03-07 11:56:16 -0600

Customer: Madison County	Unit Number: 92	
Address: PO BOX 237 Madison, FL 32340 Phone: N/A Fax: N/A Customer Number: 4806536140 Billing Customer: Madison County Board Of	Asset: 2016 Mack CHU613 Serial Number: GM021578 VIN: 1M1AN07Y0GM021578 Engine: M8	

	Parts	Core Prices	Additional Charges	Totals
1 DIAG Complaint: diag Cause: Truck came in for CEL/derate Truck needs oil thermostat bypass valve Truck also needs a def pump (def tank mounting brackets are supposed to be held on by 8 bolts but 5 out of 8 are missing and def tank is leaning down causing the def pump to rub against the transmission rupturing the pump.) after replacement of pump and fixing def tank mounting truck needs to have an aftertreatment analysis / NOx conversion test run to test the scr and def system to verify that no other issues are present Labor: \$365.40 Parts: \$50.00 -(1.0) P.T.T \$50.00 \$0.00 \$50.00				
2 CEL ON DERATED Complaint: CEL ON Cause: ENGINE OIL THERMOSTAT CONTROL VALVE Correction: REPLACE ENGINE OIL THERMOSTAT CONTROL VALVE Labor: \$548.10 Parts: \$270.24 -(1.0) Control Valve \$270.24 \$0.00 \$270.24				
3 DEF PUMP Complaint: DEF PUMP Cause: def tank mounting brackets are supposed to be held on by 8 bolts but 5 out of 8 are missing and def tank is leaning down causing the def pump to rub against the transmission rupturing the pump. Correction: REINSTALL DEF TANK BRACKETS AND REPLACE DEF PUMP Labor: \$913.60 Parts: \$2,217.65 -(6.0) FLANGE SCREW \$8.59 \$0.00 \$51.54 -(1.0) BRACKET \$32.28 \$0.00 \$32.28 -(1.0) BRACKET \$32.08 \$0.00 \$32.08 -(1.0) PUMP UNIT Core: \$731.50 \$2,101.75 \$731.50 \$2,833.25				
4 manual regen				

23131 Tri-State Truck Center - Mack (Jackson MS)

Customer: Madison County	Unit Number: 92	
Case Number: 18131478	Assot: 2016 Mack CHU613 VIN: 1M1AN07Y0GM021578	

Item	Description	Parts	Core P/ces	Additional Charges	Total
Labor:					\$182.70

Labor: \$2,009.70
 Parts: \$2,537.89
 Core: \$731.50
 Shop Supplies: \$195.95
 Freight: \$200.00
 Total: \$5,675.04

Notes:

[3/7/2023 at 02:02 pm CST] - Unit was checked in at Tri-State Truck Center - Mack (Jackson MS), arrival time: 3/7/2023 at 02:02 pm CST.
 Repair status set to Checked-In.
 [3/9/2023 at 10:07 am CST] - Approval Requested for the estimate version 1, total \$5,474.52. View the estimate.
 Repair status set to Hold (auth).
 [3/9/2023 at 10:18 am CST] - Approval Requested for the estimate version 2, total \$5,675.04. View the estimate. NOTE: revised for manual regen
 Repair status set to Hold (auth).
 [3/9/2023 at 10:24 am CST] - Approval Requested for the estimate version 3, total \$5,675.04. View the estimate.
 Repair status set to Hold (auth).

I hereby authorize the above repair work to be done with the necessary materials. You will not be held responsible for loss or damage to vehicle, or articles left in vehicle, in case of fire, theft, accident or any other cause beyond your control. I hereby grant you and your employees with permission to operate the vehicle herein described for the purpose of testing and/or inspection, an express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Please select ONE of the following terms:

(a) I request an estimate in writing before you begin repairs-

Signature _____

(b) Please proceed with repairs but call me for approval before continuing if price exceeds \$ _____

Signature _____

(c) I do not want an estimate and you may set the price for repairs.

Signature _____

Because of limited parking space, we cannot store vehicles for a lengthy period of time. Please note that effective on the sixth day following completion of repairs, a \$20 per day storage fee will be assessed until the unit is removed.