

BOARD OF SUPERVISORS

MADISON COUNTY, MISSISSIPPI


Department of Engineering
Dan Gaillet, P.E., County Engineer

3137 South Liberty Street, Canton, MS 39046
Office (601) 790-2525 FAX (601) 859-3430

MEMORANDUM

May 2, 2018

To: Sheila Jones, Supervisor, District I
Trey Baxter, Supervisor, District II
Gerald Steen, Supervisor, District III
David Bishop, Supervisor, District IV
Paul Griffin, Supervisor, District V

From: Dan Gaillet, P.E. 
County Engineer

Re: Sink Hole
105 Maple Grove
Ashbrooke Subdivision

A sink hole has formed due to the failure of a pipe that carries roadway storm water from Maple Grove to Sycamore Ridge, across private property at 105 Maple Grove.

The Engineering Department suspects that the pipes have separated which is causing a couple of dangerous sink holes. However, a full determination of damage will take place after authorization is granted to work on private property.

It is the recommendation of the Engineering Department that the Board authorize repairs to ensure that storm water is moved from point-to-point to prevent damage to the roadway and further damage to the storm water system.

Therefore, it is in the best interest of the County and the public's health, safety and welfare to make the repairs, based on:

- Separated storm water pipes;
- Water is unable to flow freely off of Maple Grove to Sycamore Ridge; and
- Large sink holes have formed over the failed pipe.

SHEILA JONES
District One

TREY BAXTER
District Two

GERALD STEEN
District Three


DAVID BISHOP
District Four

PAUL GRIFFIN
District Five

SINKHOLE FLOW CHART

LOCATION: 105 Maple Grove

DATE: 4/17/18



105 Maple Grove

WINDY GROVE

FAST FOAM



C105 MAPLE GROVE



