

Department of Engineering
Dan Gaillet, P.E., County Engineer

3137 South Liberty Street, Canton, MS 39046
Office (601) 790-2525 FAX (601) 859-3430

MEMORANDUM

June 12, 2019

To: Sheila Jones, Supervisor, District I
Trey Baxter, Supervisor, District II
Gerald Steen, Supervisor, District III
David Bishop, Supervisor, District IV
Paul Griffin, Supervisor, District V

From: Dan Gaillet, P.E.
County Engineer



Re: Sink Hole
222 Stillhouse Creek Drive

A sink hole has formed at 222 Stillhouse Creek Drive due to the failure of pipe that carries roadway storm water from Stillhouse Creek Drive, across property at 222 Stillhouse Creek Drive.

The Engineering Department has determined that the pipes have separated which is causing a dangerous sink hole and repairs be made to ensure that storm water is moved from point-to-point to prevent damage to the roadway and further damage the storm water system.

It is the recommendation of the Engineering Department that Blurton and Banks be hired to perform the repairs, for a fee not to exceed \$11,500.00.

Therefore, it is in the best interest of the County and the public's health, safety and welfare to make the repairs, based on:

- Separated storm water pipes;
- Water is unable to flow freely off of Stillhouse Creek Drive; and
- A large sink hole has formed over the pipe failure.

SHEILA JONES
District One

TREY BAXTER
District Two

GERALD STEEN
District Three

DAVID BISHOP
District Four

PAUL GRIFFIN
District Five

SINKHOLE FLOW CHART

LOCATION: 222 Stillhouse Creek Dr.

DATE: 4/12/2019







