

PURCHASING DEPARTMENT

Madison County Board of Supervisors 146 West Center Street / Post Office Box 608 Canton, MS 39046 Office (601)~855~5534 ~ Fax (601) 859~5875

March 18, 2024

To:

Board of Supervisors

From:

Kesha Jackson, Purchasing Clerk

Subject:

Consideration of Declaration of Sole Source for Mack Truck

The Madison County Road Department has requisitioned for Tri State Truck to replace the pressure regulator, injector and remove and install DPF clamp and gasket on the 2015 Mack GU713 truck. As the attached letter, indicates that Tri State Truck is the only license vendor to repair Mack trucks.

I recommend that the board declare this as a Sole Source, authorize the issuance of a purchase order to Tri State Truck for \$6,794.60 on said replacement of the pressure regulator, injector, remove and install DPF clamp and gasket on the 2015 Mack GU713 truck per the attached quote.

Thank you in advance for your consideration of the above recommendations.

ESTIMATE VERSION 3 - POSTED TO FLEET

Updated at: 2024-03-06 09:07:54 -0600

Tri-State Truck Center - Mack (Jackson MS)

412 Hwy 49 S. Richland, Mississippi 39218

Phone: (601) 932-3400

DSIST

Fax: N/A

Case Number: 18078073 Repair Order Number: 22743 Purchase Order Number: N/A

Service Advisor: Jackson MS--, --Tri-state Service - Case Date 2024-03-05 11:30:30

Customer: Madison County

Unit Number: 72-14

Address: PO BOX 237 Canton, MS Phone: N/A

39046

Customer Number: 4806536140

Billing Customer: Madison County Board Of

Asset: 2015 Mack GU713

Sorial Number: FM022302 VIN: 1M2AX04C1FM022302

Engine: MP7

Engine Hours: 13053 Odometer: 221534 Miles FM022302 Warranty Start: 2014-05-22 12:00:00 -0500

in Service: 9 Years 10 Months

((0)	Operation Name	िखा	Additional Totals (Charges)
1	Diag		
	Labor:		\$383.66
	Parts:		\$99.00
	-(1.0) (RIT) P.I.I.	\$99.00	\$99.00
2	Derated- 5 mpt/Replace Hydrocarbon Dosing Module and air regulator		
	Labor:		\$575 <i>A</i> !
	Parts:		\$969.7
	-(1.0) [23185531] MODULE Core: \$282.75	\$666.16	\$666.19
	-(1.0) (21243502) PRESSURE REGULATOR	\$303.58	\$303.5
3	Replace Seventh Injector		
	Labor:		\$383,6
	Parts:	,	\$181,3
	-(1.0) [21407621] INJECTOR 2584	\$181.38	\$181.3
4	Remove and Install DPF for cleaning or Replacement.	•	
	Labor:		\$1,055.0
	Parts:		\$2,645.6
	-(2.0) [21095726] GASKET	\$25.13	\$50.2
	-(2.0) (21021850) CLAMP	\$47.87	\$95.7
	-{1.0) [85124753] KIT, DPG CLAMP AND GASKET	\$445.23	\$445.2
	-(1.0) SUB Clean DPF	\$209.95	\$209.9
	-(1.0) [VN1205-C] 22810503 DPF FILTER	\$1,844.50	\$1,844.5
5	Manual Regen		
	Labor:		\$239.

Parts: \$3,895.80

Labor: \$2,637.67

Shop Supplies: \$261.13

Total: \$6,794.60

Notes:

Updated at: 2024-03-06 09:07:54 -0600

ESTIMATE VERSION 3 - POSTED TO FLEET

AIST Tri-State Tru	ck Center - Mack (Jackson MS)	lated at: 2024-0		ACT I COL
Customer: Madison County	Unit Number: 72-14	•		
Case Number: 18078073	Asset: 2015 Mack GU713			
	VIN: 1M2AX04C1FM022302		FMC	022302
9/5/2024 at 11:55 am CSTJ - Unit w ST, Repair status set to Checked-li	vas checked in at Tri-State Truck Center - Mack (Jackson MS), a n.	rrival lime: 3/5/	2024 at 11:	55 am
1/5/2024 at 03:48 pm CSTI - Approx	val Requested for the estimate version 1, total \$6,581.60. Repail val Requested for the estimate version 2, total \$6,151.03. NOTE	r status set to F : Correct addre	iold (auth). ss and with	out
	val Requested for the estimate version 3, total \$6,794.60. Repai	r status set to h	łold (auth).	
(tem	Declined or Deferred Operation	Delign	ितिक	වැඩිව
Steering wheel is missing m Parts:	aterial	\$191.83	\$494.99	not sold
· (1.0) STRG WHEEL-NICK	EL-	•	\$494.99	
Steering till cable broken Parts:		\$383.66	\$73.48	not solo
- (1.0) REPAIR KIT	6429		\$73.48	
ehicle, or articles left in vehicle, in c	work to be done with the necessary materials. You will not be he case of fire, theft, accident or any other cause beyond your contribute the vehicle herein described for the purposeof testing and/or we vehicle to sercure the amount of repairs thereto. Before you begin repairs-	ol. I hereby ar	ant you and	your
ignature)) Please proceed with repairs but o	call me for approval before continuing if price exceeds \$			
gnature	u may sel the price for repairs.			
gnature				
ecause of limited parking space, we				

412 Hghway 49 Swift Jackson, MS 39218 P 601 932 3400 F 601 932 3400 T 600 876 7348 Pristabeturik com



April 4,2023

To whom it may concern:

Service Manager

Tri-State Truck is the only vendor in the state of Mississippi that services Mack Trucks.

Berne t

112-5 A

15 x 19 16

Late Star No

ALESTING OF

Market Ma

क्षांत्रम हते.

"(SERVINEL TA) .

HAM. MO