




## PURCHASING DEPARTMENT

Madison County Board of Supervisors  
146 West Center Street / Post Office Box 608  
Canton, MS 39046

July 6, 2026

To: Board of Supervisors  
From: Kesha Jackson, Purchasing Clerk   
Subject: Consideration of Declaration of Sole Source

The Madison County Road Department has requisition Tri-State Truck Center-Mack to replace the fuel tank, fuel system, fuel filters, fuel base AH1 Module, the 7<sup>th</sup> injector for truck # 11881. As the attached letter, indicates that Tri-State Truck is the only vendor in the State of Mississippi that services Mack Trucks.

I recommend that the board declare this as a Sole Source, authorize the issuance of a purchase order to Tri-State Truck Center-Mack for \$19,617.88 to replace the fuel tank, fuel system, fuel filters, fuel base AH1 Module, the 7<sup>th</sup> injector for truck # 11881 per attached quote.


Thank you in advance for your consideration of the above recommendations.

**Tri-State Truck Center - Mack (Jackson MS)**

412 Hwy 49 S. Richland, Mississippi 39218  
Phone: (601) 932-3400



Case Number: 20865082  
Repair Order Number: 35051  
Purchase Order Number: N/A  
Service Advisor: Barber, Brooklen - Case Date 2026-05-19 11:24:17 -0500

<b>Customer:</b> Madison County Brd Suprvsr	<b>Unit Number:</b> N/A 11881		 SM015469
<b>Address:</b> 3137 S LIBERTY ST CANTON, MS 390468826	<b>Asset:</b> 2025 MACK PI64T	<b>Engine Hours:</b> 1471	
<b>Phone:</b> N/A	<b>Serial Number:</b> SM015469	<b>Odometer:</b> 29855 Miles	
<b>Fax:</b> N/A	<b>VIN:</b> 1M1PN4GY6SM015469	<b>Warranty Start:</b> 09/25/2024 12:00:00	
<b>Customer Number:</b> 7480710483	<b>Engine:</b> ENG-VE13	<b>In Service:</b> 1 Year 8 Months	

1 diagnostics [000-000-0000]				
Complaint: diag tag#3463 case#20865082				
	Quantity	Price	Core Price	Totals
<b>Labor:</b>	2	\$211.51	n/a	\$423.02
<b>Parts:</b> EMERGENCY HANDLING FEE	1.0	\$200.00	\$0.00	\$200.00
<b>Operation Total:</b>				\$623.02

2 check light - miss fire on 1st injector [045-000-000]				
<b>Complaint:</b> check light - miss fire on 1st injector				
<b>Cause:</b> fuel contamination				
<b>Correction:</b> We connected to PTT and found active fault codes for injector 1 offset learning at max limit and cylinder 1 misfire detected confirmed truck is running very rough Technician checked fuel tanks and the diesel is contaminated with something. It is very cloudy and has a very odd smell to it technician collected a sample and it has brown liquid that has separated to the bottom, confirmed fuel system is compromised and has now affected the injectors. See line below for repair plan				
	Quantity	Price	Core Price	Totals
<b>Labor:</b>	0	\$211.51	n/a	\$0.00
<b>Operation Total:</b>				\$0.00

3 fuel system replacement [044-000-000]				
<b>Complaint:</b> customer states engine light illuminated miss fire				
<b>Cause:</b> contaminated fuel				
<b>Correction:</b> remove and replace fuel tanks flush fuel system				
	Quantity	Price	Core Price	Totals
<b>Labor:</b>	14	\$211.51	n/a	\$2,961.14
<b>Operation Total:</b>				\$2,961.14

4 replace fuel pump [044-000-000]				
<b>Complaint:</b> customer states mis fire				

**ASIST** Tri-State Truck Center - Mack (Jackson MS)



<b>Customer:</b> Madlson County Brd Suprvsr	<b>Unit Number:</b>
<b>Case Number:</b> 20865082	<b>Asset:</b> 2025 MACK PI64T <b>VIN:</b> 1M1PN4GY6SM015469

<b>Cause:</b>	fuel contamination					
<b>Correction:</b>	remove and replace fuel pump					
		<b>Quantity</b>	<b>Price</b>	<b>Core Price</b>	<b>Totals</b>	
<b>Labor:</b>		5	\$211.51	n/a	\$1,057.55	
<b>Parts:</b>	20997341	FUEL PUMP	1.0	\$1,109.72	\$0.00	\$1,109.72
<b>Operation Total:</b>					\$2,167.27	

<b>5 injectors [045-000-000]</b>						
<b>Complaint:</b>	customer states misfire					
<b>Cause:</b>	fuel contamination					
<b>Correction:</b>	remove common fuel rail to remove injectors replace with new reinstall hardware					
		<b>Quantity</b>	<b>Price</b>	<b>Core Price</b>	<b>Totals</b>	
<b>Labor:</b>		15	\$211.51	n/a	\$3,172.65	
<b>Parts:</b>	85030561	INJECTOR Core: \$2,862.00	1.0	\$3,597.38	\$2,862.00	\$6,459.38
	22618326	SEALANT	1.0	\$93.26	\$0.00	\$93.26
	85134750	SEALANT	1.0	\$23.87	\$0.00	\$23.87
	23693934	COMMON RAIL	1.0	\$970.34	\$0.00	\$970.34
	24429533	CONNECTION PIPE	1.0	\$17.41	\$0.00	\$17.41
	<b>Parts Total</b>				\$7,564.26	
<b>Operation Total:</b>					\$10,736.91	

<b>6 fuel filter base [044-000-000]</b>						
<b>Complaint:</b>	customer states misfire					
<b>Cause:</b>	fuel contamination					
<b>Correction:</b>	remove and replace fuel filter base and AHI module					
		<b>Quantity</b>	<b>Price</b>	<b>Core Price</b>	<b>Totals</b>	
<b>Labor:</b>		3.5	\$211.51	n/a	\$740.29	
<b>Parts:</b>	24623848	FILTER HOUSING	1.0	\$758.30	\$0.00	\$758.30
	PSVC9226	CLEAR DIESEL FUEL & TANK CLEANER	2.0	\$15.47	\$0.00	\$30.94
	<b>Parts Total</b>				\$789.24	
<b>Operation Total:</b>					\$1,529.53	

<b>7 7th injector [045-000-000]</b>					
<b>Complaint:</b>	customer states misfire				
<b>Cause:</b>	fuel contamination				
<b>Correction:</b>	remove and replace 7th injector				
		<b>Quantity</b>	<b>Price</b>	<b>Core Price</b>	<b>Totals</b>
<b>Labor:</b>		2.5	\$211.51	n/a	\$528.78

**ASIST** Tri-State Truck Center - Mack (Jackson MS)



Customer: Madison County Brd Suprvsr	Unit Number:
Case Number: 20865082	Asset: 2025 MACK PI64T VIN: 1M1PN4GY6SM015469

Parts:	23937771	INJECTOR	1.0	\$191.77	\$0.00	\$191.77
Operation Total:						\$720.55

	Parts	\$6,992.99
	Labor	\$8,883.43
	Shop Supplies	\$879.46
	Core	\$2,862.00
	<b>Total</b>	<b>\$19,617.88</b>

**Notes:**

[5/19/2026 at 11:24 am CDT] - Unit was checked in at Tri-State Truck Center - Mack (Jackson MS). Arrival time: 5/19/2026 at 11:24 am CDT. NOTE: this is conformation your unit has been full checked in. we have a minimum 2 hr. assessment/diagnostic. we will update once your unit has been assigned to a technician, followed with a repair plan. customer maybe responsible for freight on parts even if it's a warranty repair. Case status set to Checked-in.

[5/28/2026 at 01:48 pm CDT] - Approval Requested for the estimate version 1. Total \$20,991.13. Repair status set to Pending Approval.

[5/28/2026 at 01:49 pm CDT] - Approval Requested for the estimate version 2. Total \$20,991.13. NOTE: Needs approval please Repair status set to Pending Approval.

[5/28/2026 at 03:01 pm CDT] - Approval Requested for the estimate version 3. Total \$19,617.88. NOTE: TAXES REMOVED Repair status set to Pending Approval.

I hereby authorize the above repair work to be done with the necessary materials. You will not be held responsible for loss or damage to vehicle, or articles left in vehicle, in case of fire, theft, accident or any other cause beyond your control. I hereby grant you and your employees with permission to operate the vehicle herein described for the purpose of testing and/or inspection. an express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Please select ONE of the following terms:

(a) I request an estimate in writing before you begin repairs-

Signature \_\_\_\_\_

(b) Please proceed with repairs but call me for approval before continuing if price exceeds \$ \_\_\_\_\_

Signature \_\_\_\_\_

(c) I do not want an estimate and you may set the price for repairs.

Signature \_\_\_\_\_

Because of limited parking space, we cannot store vehicles for a lengthy period of time. Please note that effective on the sixth day following completion of repairs, a \$20 per day storage fee will be assessed until the unit is removed.

4121 Highway 49 South  
Jackson, MS 39218  
P 601.932.3400 F 601.932.3406 T 800.870.2348  
tristatetruck.com



June 15, 2026

Tupelo MS  
Memph TN  
Jackson TN  
Little Rock AR  
Jackson AR  
Meridian MS  
Jackson MS  
Springfield MO  
Joplin MO

To whom it may concern:

Tri-State Truck is the only vendor in the state of Mississippi that services Mack Trucks.

Warm regards,

A handwritten signature in black ink, appearing to read "David Keele".

DAVID KEELE

SERVICE MANAGER