

# **BOARD OF SUPERVISORS**

Madison County, Mississippi

E-911 Administration Office

1633 W. Peace Street, PO Box 608, Canton, MS 39046

T: (601) 859-6485 F: (601) 859-4743


**DATE:** October 13, 2017  
**TO:** Madison County Board of Supervisors  
**FROM:** Emergency Management Office  
**RE:** Road Claim  
Alex Breeland

After further investigation on the above referenced claim, it is the recommendation of the Emergency Management Office to approve and pay the claim to the order of Alex Breeland, in the amount of \$ 779.58 for stated repairs. If any further information is needed, please contact our office.

*It is undetermined if the exact location has been repaired and sue to ongoing and reported problems of needed repairs on Virilia Rd.*

# ROAD CLAIM INCIDENT REPORT

In order to process the claim, please print & fill out completely and return to Madison Co. EMA office along with two signed estimates for damages being claimed. All required paperwork must be returned within 7 days of incident. NOTE: Our policy is a reimbursement policy. We DO NOT replace nor arrange to have any repairs made. It is to your own discretion to when the repairs are made. If your claim is approved a reimbursement check will be mailed to you at the given address given below.

<b>Personal Information</b>	Date: <u>09-22-2017</u> Name: <u>Alex Breeland</u> Mailing Address: <u>P.O. Box 371</u> <u>Canton MS 39046</u> Contact #: <u>601-672-5093</u> Make/ Model of Vehicle: <u>2016 Cadillac XTS</u>
<b>Incident Information</b>	Please answer questions below in relations to the incident being reported: Date: <u>09-19-17</u> Time: <u>745 AM</u> Location: <u>Virtilia Rd</u> (name of road incident occurred) Area Landmarks: <u>1/2 - 3 miles west of Hwy 22</u> Approx. Speed at time of incident: <u>35</u> Direction of Travel: <u>East</u> Cause of Incident: <u>Pothole</u> (ie: pothole, rock, etc..) Area of vehicle damaged: <u>left front tire &amp; rim/axle</u>
<b>Incident Summary</b>	Please write a brief summary of the incident (use back if needed): <u>Traveling east on Virtilia rd when I hit a pothole. No real surprise as this road is &amp; has been a disaster for 2+ years (over)</u> 

OFFICE USE ONLY:

Date Received: \_\_\_\_\_

Received by: Road 9/25/17

Dept: EMA

Estimate for tire

Superior	193.67
Manning	183.83

Estimate for wheel (rim)

George Carr	619.59
Barkside	595.75

Had tire replaced by Superior Tire.  
Then noticed car did not drive  
smooth, returned to Superior where  
they discovered the wheel (rim) was  
damaged.

*[Signature]*



# SUPERIOR TIRE RECAPPERS, INC.

TIRES - TUBES - ALIGNMENT - SERVICE

3247 S. Liberty Street  
P.O. Box 188

Phones 859-2432  
859-2433

CANTON, MISS. 39046-0188

1.5% FINANCE CHARGE AFTER 30 DAYS

Customer's Name: Breeland Funeral Home Date: 9-19-17  
 Order No.: \_\_\_\_\_  
 Address: \_\_\_\_\_

ONE #	CASH	C.O.D.	CHARGE	ON ACCT.	MDSE. RETD.	PAID OUT
	✓					(7)

QTY.	DESCRIPTION	PRICE	AMOUNT
1	245/45R19 Cygan Eagle RS-A Radial		178 <sup>00</sup>
	SHOP SUPPLIES		3 <sup>00</sup>
	WASTE TIRE DISPOSAL FEE		12 <sup>67</sup>
All claims and returned goods MUST be accompanied by this bill.			7% TAX
			1.5% TAX
L98104 Received By		TOTAL 193 <sup>67</sup>	

*PD*  
*CK# 7119*



PO #:

Date: 21-September-2017

© 2017 General Motors

Account #:

Dealer Information	Customer Information
Name: George Carr	Name: BRELAND FUNERAL HOME
Address: 2950 South Frontage Road Vicksburg, Ms 39180 United States	Address:
Phone: 6016367777	Phone: 601-859-3661
Fax:	Email:
Contact: George Carr	Contact: Alex <sup>Breeland</sup> Freeman

Vehicle Information

VIN: 2G61M5S32G9169436      Vehicle: K - Cadillac > 2016 > G - XTS

Item	Description	Qty	Unit Price	Price
1	WHEEL, FRT & RR (STERLING SILVER) (19 X 8.5)	4	0.00	\$54.00

Labor 38.00

Shipping Method:

Shipping:

Tax Rate:

Subtotal:

Tax:

Total:

\$579.06~~00~~

4253~~000~~

\$619.59 0.00

Dealer Message:

2950 South Frontage Road  
Vicksburg, Ms 39180  
United States  
brandoncarr@yahoo.com  
Phone: 6016367777

Estimate for tire

Superior	193.67
Manning	183.83

Estimate for wheel (rim)

George Carr	619.59
Bartsdale	595.75

Had tire replaced by Superior Tire.  
Then noticed car did not drive  
smooth, returned to Superior where  
they discovered the wheel (rim) was  
damaged.

*[Signature]*

**BARKSDALE CADILLAC**

SEP 21, 2017 APPOINTMENTS

Store 01 SERVC01 346/5030 3010

```

+-----+
| CUSTOMER NO 40041 [GRID] SERIAL NO 2G61M5S32G9169436 |
| NAME ALEX BREELAND MAKE CD CADILLAC |
| BUS. PHONE NO 601-672-5093 YEAR 16 |
| RES. PHONE NO 601-859-3661 MODEL XTS |
| DEPT (S,B,P) S SERVICE LICENSE NO MEG166 |
| ADVISOR NO 335 DEBBIE K BARRETT STOCK NO |
| MILEAGE 35000 LAST MILEAGE 34984 |
| APPT./PROM. DATE 09/22/2017/ 09/22/2017 LAST RO DATE 08/03/2017 |
| APPT./PROM. TIME 07:00am / 06:00pm |
| ESTIMATE(P/L/T) / / 0.00 VEH. PRIORITY 1 |
| PICKUP / DISPATCHER# 1 TEAM CODE: |
| COMMENT |
| JOB OPERATION DESCRIPTION CWI PR EST.TIME TECH $QUOTE |
| * 1 01CDZINSP GM MULTI-POINT C 99 0.1 0.00 |
| 2 05CDZ WHEELS & TIRES C 50 0.5 0.00 |
+-----+
    
```

539.98  
23232107  
(B)

1=CUST. 2=VEH 3=HIST 4=REC. SVC. 5=COMP 6=APPT. SCHED. 7=SHOP CAP 8=RTE SHEET  
 9=SVC.OP.DISP 10=APPT. LOG 11=EST 12=QUOTE 13=APPT. CNTRL 14=WE OWE  
 (E=ENTER)(CR=CONS REACH)(C=CHANGE)(A=ADD)(D=DELETE)(LINE#)(N=NOTE)(TAB)

Labor 15.00  
 sheet @ 23232107 - 539.98  
 Shop Supp 1.80  


---


 Total 595.75



September 21, 2017

To Whom It May Concern;

After having replaced the front tire on the Cadillac owned by Alex Breeland it was discovered that the rim was also bent and would need to be replaced.

  
Herman Mosby  
Superior Tire

