

BOARD OF SUPERVISORS

Madison County, Mississippi

Emergency Management Office

1633 W. Peace Street, PO Box 608, Canton, MS 39046

T: (601) 859-6485 F: (601) 859-4743

DATE: January 28, 2019
TO: Madison County Board of Supervisors
FROM: Emergency Management Office
RE: Road Claim
Lauren Coon

After investigation on the above referenced claim, it is the recommendation of the Emergency Management Office to approve and pay the claim to the order of Lauren Coon, in the amount of \$ 109.83 for stated repairs. If any further information is needed, please contact our office.

*Repairs not completed within 7- day period allowed per Madison County Road Claim Policy.
Per Madison County Road Dept., road in need of extensive repairs.*

ROAD CLAIM INCIDENT REPORT

In order to process the claim, please print & fill out completely and return to Madison Co. EMA office along with two signed estimates for damages being claimed. All required paperwork must be returned within 7 days of incident. NOTE: Our policy is a reimbursement policy. We DO NOT replace nor arrange to have any repairs made. It is to your own discretion to when the repairs are made. If your claim is approved a reimbursement check will be mailed to you at the given address given below.

Personal Information	Date: <u>Jan 14, 2019</u> Name: <u>Lauren Coon</u> Mailing Address: <u>439 Chapel Hills Road, Flora, MS 39071</u> Contact #: <u>601 551-0982</u> Make/ Model of Vehicle: <u>2014 Nissan Altima</u>
Incident Information	Please answer questions below in relations to the incident being reported: Date: <u>Jan 14, 2019</u> Time: <u>7:15 Am</u> Location: <u>Gus Green Road</u> <small>(name of road incident occurred)</small> Area Landmarks: <u>Big potholes just north of Elverse Jones drive</u> Approx. Speed at time of incident: <u>25</u> Direction of Travel: <u>South</u> Cause of Incident: <u>Hit big pothole - couldn't avoid due to oncoming traffic</u> <small>(ie: pothole, rock, etc..)</small> Area of vehicle damaged: <u>Blew out drivers tire, damaged Rim and wheelcover</u>
Incident Summary	Please write a brief summary of the incident (use back if needed): There are several severe potholes on Gus Green, this morning we hit one on drivers tire while driving at low speed 25 mph. Couldn't avoid it due to oncoming traffic. Tire blew out, wheel cover flew off and is broken.
Signature	<u>Lauren Coon</u> <u>1/16/2019</u> Signature Date <input checked="" type="checkbox"/> Please check box, indicating that you have read and understand the Madison Co. Road Claim Policy:

1-17-19 sent Helen/Coon email regarding claim - JK

OFFICE USE ONLY:

Date Received: 1/17/19 Received by: JK via email Dept: _____




601-365-0843

Your Store: **Jackson, MS** 6371 Interstate 55

Tires Tire Brands Auto Service Specials & Rebates Careers

CBorn

Item Description	Availability	Qty	Price Each	Item Total
 Toyo Celsius PCR 215/60HR16 95H BK 440AA SL 4 Installation Center Overhead and Stocking Fee*	In Stock	1 ▼	\$119.00	\$119.00
			\$0.99	\$0.99
Tire Price			\$119.99	\$119.99
*Includes				
✔ Shipping to store location of your choice				
✔ Dismounting of old tire, mounting of new tire				
✔ Proper Lug Nut Torquing to manufacturer specification				
✔ 30-Day Price Guarantee				
✔ Free Lifetime Rotation				
Computer Balance Package more			\$21.99	\$21.99
Total Price			\$141.98	\$141.98
			Cart Total: \$141.98 (before taxes)	

Lance Cow

CLUB# 08271
 257 GRANDVIEW BLVD
 MADISON, MS 39110 US
 (601)977-0139



COYNE

COYNE, BILLY
 439 CHAPEL HILLS RD, FLORA, MS 39071

MAKE NISSAN/DATSUN	MODEL ALTIMA	COLOR Black
ODOMETER 106755	MEMBER ARRIVAL TIME 2019-01-16 05:02 PM	SERVICE COMPLETED TIME 2019-01-16 05:17 PM

Service Description	Service
TIRE INSTALL PACKAGE Whitewall - N/A - Tire Pressure - Drv Front - CHECKED, 35 - Tire Pressure - Pass Front - CHECKED, 35 - Valve Stem - Pass Front - COMPLETE - New Tire - Pass Front - COMPLETE - Dispose Tire Accepted - Pass Front - COMPLETE LUG TORQUE Pass Front 90 FT-LB TREAD DEPTH Pass Front - 11/32	15.00
- Tire Pressure - Drv Rear - CHECKED, 35 - Tire Pressure - Pass Rear - CHECKED, 35 - Balance Accepted - Pass Front - COMPLETE - DOT Number - Pass Front - U1063118 - SAMS Battery Check - TESTED GOOD	

Lamar Con

Merchandise Description	Quantity	Unit Price	Merchandise
P215/60R16 95T P4FS+	1	94.83	94.83

Member Comments	Total (Excluding Tax & Govt. Fees) 109.83
Technician Comments	<p>PLEASE READ IMPORTANT INFORMATION BELOW AND ON REVERSE</p> <p>DISCLAIMER & ACKNOWLEDGMENT</p> <p>I authorize the stated service completion and give permission to operate the vehicle</p> <p>1. Sam's Club is not responsible for loss/damage to the vehicle or items left in it</p> <p>2. When performing tire services or non-tire related services such as battery, wiper, or any other services, Sam's Club does not perform any tire inspections other than those indicated on this Service Order. Unless indicated on the Service Order, Sam's Club associates do not inspect the spare tire, if any</p> <p>3. Members should follow vehicle and tire owner's manuals guidance and frequently check tires for proper inflation pressure, tread depth (more than 2/32" in all grooves) and conditions like tire age, cuts, punctures, cracking, bulges and uneven tread wear</p> <p>Driving conditions and vehicle operation may affect the safety and performance of my tires</p> <p>I have read, understand and accept all provisions of the disclaimer and acknowledgment above and the warranty statement on the reverse covering parts and service on this vehicle</p>
	01-16-2019
MEMBER SIGNATURE	DATE

Actual amount paid due to pot hole

BATTERY TECHNICIAN: EUGENE AS
 COMMON TECHNICIAN: EUGENE AS
 QUALITY CONTROL TECH: DARREN 3626
 SALES ASSOCIATE: ANGELA 3991
 TIRE TECHNICIAN: EUGENE AS

HAVE YOUR LUG NUTS RETORQUED AFTER THE FIRST 50 MILES.