



Figure 1 – Health Center Building



Figure 2 –Porch of the Health Center



Figure 3 – Health Center Porch



Figure 4 – Great Room in the Health Center



Figure 5 – Hood installed in the Kitchen



Figure 6 – Wood base installed in the office of the health center




Figure 7 – Contractors have started install restroom vanities



Figure 8 – Wall tile installed in both bathrooms of the health center



Figure 9 – Exterior View of the Restroom Building



Figure 10 – Exterior view of the pavilion



Figure 11 – Lighting fixtures and fans being installed at the pavilion



Figure 12 – Brick columns installed at the pavilion