

BOARD OF SUPERVISORS

Madison County, Mississippi


E-911 Administration Office

146 W. Center Street, Room 203, PO Box 608, Canton, MS 39046

T: (601) 859-6485 F: (601) 859-4743

DATE: August 28, 2013

TO: Madison County Board of Supervisors

FROM: Butch Hammack
Emergency Management Office 

RE: Road Claim
Michelle Rushing

After further investigation on the above referenced claim, it is the recommendation of the Emergency Management Office to approve and pay the claim to the order of Michelle Rushing in the amount of \$837.70 (the lesser of the two attached quotes) for stated repairs. If any further information is needed, please contact our office.

The damaged was caused by county equipment. Vehicle was stopped at time of incident allowing county equipment to pass. No signage present.

ROAD CLAIM INCIDENT REPORT

In order to process claim, please print & fill out completely, then return to Madison County Road Dept. or Madison Co. EMA office along with two signed estimates for damages being claimed.

<p>Personal Information</p>	<p>Date: <u>August 27, 2013</u></p> <p>Name: <u>Michelle Rushing</u></p> <p>Mailing Address: <u>170 Harvey Xing Canton, MS 39046</u></p> <hr/> <p>Contact #: <u>(601)421-9213</u></p> <p>Make/ Model of Vehicle: <u>2008 Honda Accord</u></p>
<p>Incident Information</p>	<p>Please answer questions below in relations to the incident being reported:</p> <p>Date: <u>August 19, 2013</u> Time: <u>2:30 pm</u></p> <p>Location: <u>Yandell Rd</u> (name of road incident occurred)</p> <p>Area Landmarks: <u>Hampton Hill Subdivision</u></p> <p>Approx. Speed at time of incident: <u>Stopped</u></p> <p>Direction of Travel: <u>East</u></p> <p>Cause of Incident: <u>ROCKS</u> (ie: pothole, rock, etc..)</p> <p>Area of vehicle damaged: <u>Drivers side of vehicle</u></p>
<p>Incident Summary</p>	<p>Please write a brief summary of the incident (use back if needed):</p> <p>Mowers were cutting grass (no signage was displayed) I stopped my vehicle to let mower cross road the driver of the tractor did not lift the mower deck and when mower reached northern edge of road ROCKS were hit which in turn hit my vehicle. I was on the way to a doctor's appointment and was unable to stop and talk to the driver. I did call Helen Keller at the Road Department who did an oral report.</p>

OFFICE USE ONLY:

Date Received: 8/26/13 Received by: JU Dept: EMA

MADISON COUNTY DEPARTMENT OF ROAD MANAGEMENT
VEHICLE /EQUIPMENT ACCIDENT FORM

Contact Person: Helen Keller Phone: 601-855-5673
Date of Accident: 8/19/13
LOCATION OF ACCIDENT: Yandell Road
TIME OF ACCIDENT: 2:25 p.m.

NARRATIVE REPORT/SUMMARY OF ACCIDENT:

CLAIMANT SAYS County tractor threw rocks on her vehicle while mowing the roadside

Driver's Name: unknown DOB:
 Last Name, First Name MI M/D/Y

Driver's License No. State:

Address:

Telephone Number: Office: Home:

Check one: County Vehicle County Equipment Inventory Number

Vehicle/Equipment Identification Number:

Year: Make: Model:

Description of Injuries, if any:

Damages to Your Vehicle:

Authority Notified:

Were Pictures Taken: Yes No

Officer's Name: Report or File Number:

OTHER PERSON(S) INVOLVED

Name: Michelle RUSHING DOB:

Address: 170 Harvey Crossing, Canton, MS 39046

Driver's License Number:

Work #: Home #: Other # 601-421-9213

VEHICLE INVOLVED

Is this a county vehicle/piece of equipment? yes no

Vehicle Identification Number: Lic Plate Number:

Year: 2008 Make: Honda Model: Accord

Description of Injuries, if any:

Damages to Vehicle:

Injuries: Nature: Fatality:

Hospital: City: State:

Vehicles Towed:

Note: She did stop the operator and she could not provide A tractor number.

BARNETT'S BODY SHOP, INC

Workfile ID: 5a6a4600

264 HWY 51, RIDGELAND, MS 39157

Phone: (601) 856-0700

FAX: (601) 856-4292

Preliminary Estimate

Customer: RUSHING, MICHELLE

Job Number:

Written By: Danny Graves

Insured: RUSHING, MICHELLE

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact:

Owner:

RUSHING, MICHELLE

Inspection Location:

BARNETT'S BODY SHOP, INC
264 HWY 51
RIDGELAND, MS 39157
Repair Facility
(601) 856-0700 Day

Insurance Company:

VEHICLE

Year: 2008

Body Style: 4D SED

VIN: JHMCP26728C055552

Mileage In:

Make: HOND

Engine: 4-2.4L-FI

License:

Mileage Out:

Model: ACCORD EX

Production Date:

State:

Vehicle Out:

Color: Int:

Condition:

Job #:

TRANSMISSION

Automatic Transmission

Overdrive

POWER

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

Heated Mirrors

Power Driver Seat

DECOR

Dual Mirrors

Console/Storage

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

Satellite Radio

CD Changer/Stacker

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

ROOF

Electric Glass Sunroof

SEATS

Cloth Seats

Bucket Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control

Stability Control

Power Trunk/Gate Release

Preliminary Estimate

Customer: RUSHING, MICHELLE

Job Number:

Vehicle: 2008 HOND ACCORD EX 4D SED 4-2.4L-FI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT DOOR					
2	*	Rpr LT Door shell (HSS)		0	0.00	3.0	2.0
3		Add for Clear Coat		0	0.00	0.0	0.8
4	R&I	LT Belt molding		0	0.00	0.3	0.0
5	R&I	LT R&I mirror		0	0.00	0.3	0.0
6	R&I	LT Handle, outside painted, US built beige		0	0.00	0.4	0.0
7	R&I	LT R&I trim panel		0	0.00	0.3	0.0
8	#	Repl Cover car		1	5.00	0.2	0.0
9	#	Subl Hazardous waste removal		1	5.00	0.0	0.0
10		FENDER					
11	Blnd	LT Fender		0	0.00	0.0	1.0
12		FRONT LAMPS					
13	R&I	LT Headlamp assy		0	0.00	0.5	0.0
14		FRONT BUMPER					
15	R&I	R&I bumper cover		0	0.00	1.0	0.0
16	#	Refn Feather edge prime and block		0	0.00	0.0	1.0
17	#	Refn Denlb and Buff		0	0.00	0.0	0.8
SUBTOTALS					10.00	6.0	5.6

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			10.00
Body Labor	6.0 hrs @	\$ 50.00 /hr	300.00
Paint Labor	5.6 hrs @	\$ 50.00 /hr	280.00
Paint Supplies	5.6 hrs @	\$ 38.00 /hr	212.80
Body Supplies	3.2 hrs @	\$ 2.00 /hr	6.40
Subtotal			809.20
Sales Tax	\$ 809.20 @	7.0000 %	56.64
Grand Total			865.84
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			865.84

This is a preliminary estimate. Additional changes to the estimate may be required for the actual repair.

Preliminary Estimate

Customer: RUSHING, MICHELLE

Job Number:

Vehicle: 2008 HOND ACCORD EX 4D SED 4-2.4L-FI

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide ARG4443, CCC Data Date 8/16/2013, and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM or A/M. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2014 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a complete list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

**CAPITOL BODY SHOP OF
RIDGELAND INC.**

Workfile ID: 10f12ce6
Federal ID: 870712621

Expect Miracles
209 SUNNY BROOK RD, RIDGELAND, MS 39157
Phone: (601) 856-5411
FAX: (601) 856-9557

Preliminary Estimate

Customer: RUSHING, MICHELLE

Job Number:

Written By: Wes Hampton

Insured: RUSHING, MICHELLE
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
RUSHING, MICHELLE

(601) 421-9213 Cell

Inspection Location:
CAPITOL BODY SHOP OF RIDGELAND
INC.
209 SUNNY BROOK RD
RIDGELAND, MS 39157
Repair Facility
(601) 856-5411 Business

Insurance Company:

VEHICLE

Year: 2008	Body Style: 4D SED	VIN: JHMCP26728C055552	Mileage In:
Make: HOND	Engine: 4-2.4L-FI	License:	Mileage Out:
Model: ACCORD EX	Production Date:	State:	Vehicle Out:
Color: Int:	Condition:	Job #:	

TRANSMISSION

Automatic Transmission
Overdrive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Telescopic Wheel

RADIO

AM Radio
FM Radio

Stereo

Search/Seek
Auxiliary Audio Connection
Satellite Radio
CD Changer/Stacker

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

ROOF

Electric Glass Sunroof

SEATS

Cloth Seats
Bucket Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
Power Trunk/Gate Release

Preliminary Estimate

Customer: RUSHING, MICHELLE

Job Number:

Vehicle: 2008 HOND ACCORD EX 4D SED 4-2.4L-FI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER					
2	R&I	R&I bumper cover				1.0	
3		FRONT LAMPS					
4	R&I	LT Headlamp assy				0.5	
5		FENDER					
6	Blnd	LT Fender					1.0
7		FRONT DOOR					
8	*	Rpr LT Door shell (HSS)				3.0	2.0
9		Add for Clear Coat					0.8
10	R&I	LT Belt molding				0.3	
11	R&I	LT R&I mirror				0.3	
12	R&I	LT Handle, outside chrome				0.4	
13	R&I	LT R&I trim panel				0.3	
14		REAR DOOR					
15	Blnd	LT Door shell (HSS)					1.0
16	R&I	LT Handle, outside chrome				0.4	
17	R&I	LT R&I trim panel				0.3	
18	#	Subl Hazardous waste removal		1	5.00		
19	#	Repl Cover car		1	12.50		
20	#	Repl Corrosion protection		1	18.00		
SUBTOTALS					35.50	6.5	4.8

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			35.50
Body Labor	6.5 hrs @	\$ 50.00 /hr	325.00
Paint Labor	4.8 hrs @	\$ 50.00 /hr	240.00
Paint Supplies	4.8 hrs @	\$ 38.00 /hr	182.40
Subtotal			782.90
Sales Tax	\$ 782.90 @	7.0000 %	54.80
Grand Total			837.70
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			837.70

Preliminary Estimate

Customer: RUSHING, MICHELLE

Job Number:

Vehicle: 2008 HOND ACCORD EX 4D SED 4-2.4L-FI

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide ARG4443, CCC Data Date 8/16/2013, and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM or A/M. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2014 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a complete list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.